



Figure 3.1-8a. Existing conditions as viewed from northbound River Road looking northwest towards Parcel D (wine tasting facility).



Figure 3.1-8b. Visual simulations as viewed from northbound River Road looking northwest towards Parcel D (wine tasting facility).

FIGURE 3.1-8
VIEWPOINT #6 – EXISTING CONDITIONS AND VISUAL SIMULATIONS