Monterey County Health Department Environmental Health Division Emergency Response Incident Report Proposition 65 Notification

MCHD # 21-009 CO22836

Incident Date: 2/1/21				Incident Time: 10:20 AM			
Incident Type:	Suspected	Hazardous Material Suspected Bioterrorist Threat Clandestine Drug Lab			☐ Sewage☐ Restaurant Fire☐ Other: <u>Hydraulic Oil</u>		
Time Notified: 11:	10 AM		5	Time Completed: 1:30 PM			
Location: 7700 Sa	ndholdt Rd.			City: Moss Landing			
Hazardous Materi	al: Hydraulic Oi	il		Quantity: 1 Gallons			
Physical Properties:				Physical / Health Hazards:			
I I and liee: I ommercial		Direct/Constructor Found: Yes				Entered Storm Drain System/Receiving Waters: Yes	
Environment Affected: Moss Landing Harbor				Weather / Temperatur Sunny/Clear ~ 60°F		Weather / Temperature: Sunny/Clear ~ 60°F	
Type of Container: Crane oil reservoir							
First Responder / Agency on Scene: N/A							
Incident Commander: N/A			Ager	Agency / Telephone: () -			
Other Responding	Personnel / Aç	gencies / Telepho	one:				
Moss Landing Harbor Master's Office Tommy Razzeca/Harbor Master 7881 Sandholdt Rd., Moss Landing (831)633-5417					() -	
Source Investigation Conducted? Yes				Source Identified? Yes			
Responsible Part Information: - Invoice	Mailing 95039	Monterey Bay Research Institute, c/o Andrew McKee Mailing Address: 7700 Sandholdt Rd. City, State, Zip Code: Moss Landing, CA 95039 (360)220-4659 , E-Mail:					
Vehicle Information	ehicle Information: O.E.S. Control #: 2			-0582 NRC #: 1297136		NRC #: 1297136	
Other Notifications:	TO STORE AND DESIGN PARTIES AND STANDARD		en instrumentation cons				

			Hazar	dous Material Incident Report - Page 2			
☐ RWQCB	☐ Air District	☐ MRWPCA	⊠ DFG	□NOAA			
☐ Cal-EMA	☐ FED EPA	□DHS	☐ Health Officer				
Narrative: We received a CalOES report about an oil spill by Moss Landing Harbor about 11:10 am on Monday, February 1st. I called Tommy Razzeca, Harbor Master at Moss Landing Harbor, around 1 pm if they are aware of the hydraulic spill from a crane that was reported on CalOES from Monterey Bay Research Institute, he said my call was the first time it was brought to his attention. He stepped out of his office while on the call with me to check out the harbor. Tommy indicated there is indeed a boom on the harbor, and that he would investigate further. I called Tommy back after 30 minutes, he reported that he didn't see any sheen on the water and that the responsible party was conducting the cleanup.							
Incident Status:							
☐ Referred to other Agency or Department for follow-up: Contact information: Action taken:							
	mpleted By: Donr	Poti ar, R. E. H. S					
1.45050	(0507/5) (7/4 7/4						

I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT

TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.
Ric Encarnacion, Acting
Bureau Chief

Bureau Chief

Bureau Chief

DN: cn=Ric Encarnacion, Acting Bureau Chief, o=County of Monterey, ou=Environmental Health Bureau, emal=encarnacion(esco.monterey, caus, c=US Date: 2021.02.03 09:03:32 -08:00'

213

2/3/2021

Ric Encarnacion, REHS, MPH

Date

Acting Director of Environmental Health

ACTIVITY LOG							
Date	Activity	Specialist	Start	Stop	Total		
2/1/21	Initial Investigation	D. Poticar	1:00 PM	1:30 PM	0.5		
2/2/21	Report Writing	D. Poticar	8:30 AM	9:00 AM	0.5		

MCHD 21 - 009

CO - 22836

make your selection - TOTAL:		1.0

MCHD 21 - 009 , CO -22836

Tons

21-009 CO-22836

Governor's Office Emergency Services

Hazardous Materials Spill Report

RECEIVED BY: CONTROL#: **DATE:** 02/01/2021 **TIME: 1055** Cal OES - 21-0582

NRC - 1297136

1.a. PERSON NOTIFYING Cal OES:

1. NAME: 2. AGENCY: **3. PHONE#: 4. Ext:** 5. PAG/CELL:

ECM Maritime

1.b. PERSON REPORTING SPILL (If different from above):

1. NAME: 2. AGENCY: **3. PHONE#:** 4. Ext: 5. PAG/CELL:

2. SUBSTANCE TYPE:

b.QTY:>=<Amount c. TYPE: 2. a. Measure d. f. VESSEL OTHER: PIPELINE >= 300 SUBSTANCE:

Gal(s) 1. Hydraulic = **PETROLEUM** No No

Oil

2. = No No **3.** No No

g. DESCRIPTION: RP states that a deck crane ruptured a hydraulic line causing a

release of less than a gallon of hydraulic oil. The release has been

stopped and contained.

j. WATERWAY: k. DRINKING WATER h. i. WATER

STOPPAGE/CONTAINMENT:INVOLVED: **IMPACTED**

Stopped, Contained Yes Moss Landing Bay

I. KNOWN IMPACT

3. a. INCIDENT LOCATION: 7700 Sandholdt Rd.

c. COUNTY: d. ZIP: **b.** CITY:

Moss Landing MONTEREY BAY UNIFIED Monterey

> County **APCD**

4. INCIDENT DESCRIPTION:

a. DATE: b. TIME c. SITE: d. REPORTED CAUSE

(Military):

02/01/2021 Waterways 1020 Mechanical

f. FATALITY g. EVACUATION h. CLEANUP BY: e. INJURIES

No No No Responsible Party

6. NOTIFICATION INFORMATION:

b. OTHER ON SCENE: c. OTHER NOTIFIED: a. ON SCENE:

e. SEC. AGENCY: d. ADMIN. AGENCY: Monterey County

Health Department

f. ADDITIONAL COUNTY: g. ADMIN. AGENCY:

h. NOTIFICATION LIST:

i. Cal GEM: j. RWQCB Unit:3

k. Cal OES Region:

AA/CUPA, DTSC, RWQCB, US EPA, USFWS, DFG-OSPR, PARKS & REC, UCSB, Co/Hlth, Co/E-Hlth

Photo Attachment:

11. Cal OES Reg.

****** Control No: 21-0582 *******

Created by: Warning Center on: 02/01/2021 10:55:25 AM Last Modified by: Warning Center on: 02/01/2021 11:05:25 AM

MCHD # 21-009 CO-22836